

FITNESS CERTIFICATE

To be filled by the Inspection Officer (Assistant Engineer)
(Re: G.O.Ms, 20/70/PWD Dt 23-01-1970)

- 1 Name of the officer
2 Name of School
3 Location with name of Education district subdistrict
4 Classification of building as per specified In col.4 of the application for fitness certificate and size

- BINDU K C
- PRABHATH PUBLIC SCHOOL
- Udayamperoor
- Ernakulam
- Tripunitura

12 Nos	6.20 x 6.0 x 3.5 - GF
12 Nos	6.20 x 6.0 x 3.5 - FF
1 No	6.20 x 6.0 x 3.5 - OFFICE
8 Nos	6.20 x 6.0 x 3.5 - GF
8 Nos	6.20 x 6.0 x 3.5 - FF

- 5 Period for which the certificate is issued
6 Nature of defect if any
a) Foundation and basement
b) super structure
c) door and windows
d) wood work wrought and put up
e) roof
F) Flooring
g) Miscellaneous (cracks etc.)
7 Any major defects modified which will render the building unsafe in any manner
8 Whether maintenance work have been done properly
whether the structure is sound or not for
9 conduction classes

- 2025-26
- Nil
- Nil
- Nil
- Nil
- Nil
- Nil
- Nil
- Nil
Nil
- Yes
The Structure is sound under normal weather condition

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

Certified that the institution was inspected by me on 02/06/2025 and found to be fit to conduct classes, for the period 2025-26 for the reason stated above.

Udayamperoor
03-06-2025



Bindu K C
Assistant Engineer
BINDU.K.C
ASSISTANT ENGINEER
PEN: 402576, LID & EW SECTION
UDAYAMPEROOR GP
Ph: 9995578013


PRINCIPAL
PRABHATH PUBLIC SCHOOL
UDAYAMPEROOR, P. O., PIN-682 307
ERNAKULAM DISTRICT, KERALA STATE



Silvy Jacob
MANAGER
PRABHATH PUBLIC SCHOOL
Udayamperoor, P. O., Pin-682 307
Ernakulam (Dist.), Kerala State